


**massive**

Soil structure descriptor indicating a lack of distinct soil aggregates; material is a coherent mass {not necessarily cemented}, no secondary pores.

*massive images/graphics:*



**Soil structure and water movement**